

Product End-of-Life (EOL) Notification

<p>AFFECTED PART NUMBER(S): LZ4-00SW08-xxxx; LZ4-40SW08-xxxx; LZ9-00SW00-xxxx; LZ9-J0SW00-xxxx; LZ9-M0SW00-xxxx; LZC-00SW00-xxxx; LZC-70SW00-xxxx; LZC-C0SW00-xxxx; Lzp-00SW00-xxxx; Lzp-D0SW00-xxxx;</p>	<p>EOL No. 00014</p>
<p>PART DESCRIPTION: Studio White emitters on LZ4, LZ9, LZC, and Lzp platform</p>	<p>DATE: 2/23/2015</p>
<p>RECOMMENDED REPLACEMENT PART NUMBER(S): No replacement as a standard catalog product. May continue to be supported as a non-standard custom order on a case by case basis.</p>	
<p>REASON FOR EOL: Insufficient demand</p>	
<p>LAST ORDER DATE: Existing orders will be fulfilled.</p>	<p>LAST SHIPMENT DATE:</p>
<p>DISPOSITION OF EXISTING INVENTORY: Use up current inventory</p>	
<p>NOTE:</p>	
<p>CONTACT PERSON: <i>Ishita Goswami</i> <i>Product Manager</i> <i>651 River Oaks Parkway</i> <i>San Jose, CA 95134</i> <i>etjahjono@ledengin.com</i></p>	