

Product End-of-Life (EOL) Notification	
AFFECTED PART NUMBER(S): LTB2-DMX1	EOL No. 25
PART DESCRIPTION: LuxiTune daughter card for DMX-512A	DATE: 11/20/2018
RECOMMENDED REPLACEMENT PART NUMBER(S): LTB6-RDM1	
REASON FOR EOL: The RDM card can support both DMX-512A and DMX-RDM modes of operation. The RDM card is also isolated and recommended for use in installations where there might be DMX grounding issues.	
LAST ORDER DATE: 5/31/2019	LAST SHIPMENT DATE: At or after 5/31/19, as needed for last time buys
DISPOSITION OF EXISTING INVENTORY: Use up existing inventory.	
NOTE:	
CONTACT PERSON: Ishita Goswami Product Manager 651 River Oaks Parkway San Jose, CA 95134 i.goswami@osram.com	