

Light is OSRAM

OSRAM

Our Brand

LED ENGIN



Product End-of-Life (EOL) Notification

Affected Part Number(s):	EOL No.
LZ1-00UV00-0100; LZ1-10UV00-0100; LZ1-30UV00-0100; LQ1-b0UV00-0100 where b = 0, 1, 3	26

Part Description:	Date:
LuxiGen LZ1 UV 365nm emitter; LuxiGen LZ1 UV 365nm emitter on MCPCB; custom variants	5/6/2019

Recommended Replacement Part Number(s):
LZ1-00UV0R-0000; LZ1-10UV0R-0000; LZ1-30UV0R-0000

Reason for EOL:
Die supplier has a planned EOL and is upgrading to a newer

Last Order Date:	Last Shipment Date:
8/1/2019	11/30/2019

Disposition of Existing Inventory
Use up current inventory. No returns to factory.

NOTE:

The replacement part is a new part number, with reversed electrical pinout and new datasheet. For the new LED emitter, rotating the emitter 180 degree allows the emitter anode and cathode match pinouts on an existing board

CONTACT PERSON:

Ishita Goswami
Product Manager
651 River Oaks Parkway
San Jose, CA 95134
i.goswami@osram.com
www.osram.us/ledengin