

OT Programmer 2.22.0.0 Release Notes

November 17, 2021

Introduction

- This document provides a set of notes for the latest release of the OT Programmer Software

Changes/Updates:

- Added Outdoor OTi180W HV+ and OTi100W 277-480V family of drivers
- Improved performance

- Download the installation file from the Digital Systems [website](#)
- Run the installation file
- Uninstallation of the previous version is not recommended to ensure that the user settings (profile folder location, data log folder location, driver filters) remain unchanged
- However, please uninstall any BETA version before installing this official released version
- Please note that administrator rights may be needed to install the program

Software

- If the user is running the previous versions of the software, a notification will appear on the status bar. Click on the link and follow the steps to update the software