



## Product End-of-Life (EOL) Notification

<b>AFFECTED PART NUMBER(S):</b> LZC-03MC00 LZC-83MC00	<b>EOL No.</b> <p style="text-align: center;">23</p>
<b>PART DESCRIPTION:</b> LZC RGB Emitter LZC RGB Emitter on 3-Ch MCPCB	<b>DATE:</b> <p style="text-align: center;">7/1/2016</p>
<b>RECOMMENDED REPLACEMENT PART NUMBER(S):</b> LZC-03MD07/ LZC-03MA07: LZC RGBW/ RGBA Emitter LZC-B3MD07/ LZC-B3MA07: LZC RGBW/ RGBA Emitter on 4-Ch MCPCB	
<b>REASON FOR EOL:</b> Market demand have shifted from 3-color LED emitter to 4-or-more-color LED emitter.	
<b>LAST ORDER DATE:</b> <p style="text-align: center;">7/31/2016</p>	<b>LAST SHIPMENT DATE:</b> <p style="text-align: center;">8/31/2016</p>
<b>DISPOSITION OF EXISTING INVENTORY:</b> LED Engin will not support this product after 8/31/2016	
<b>NOTE:</b> <p style="text-align: center;">N/A</p>	
<b>CONTACT PERSON:</b> Erin Tjahjono Product Manager 651 River Oaks Parkway San Jose, CA 95134 etjahjono@ledengin.com	